



GEORGIA FOUNTAIN COMPANY, INC.
2513 Royal Place
Tucker, GA 30084 USA

Telephone +1 770.934.3297
Fax +1 770.934.8770
Email: info@georgiafountain.com

TECH LETTER 10/2017:

MAINTENANCE ISSUES

As can be seen in the pictures below is **THE TOTAL DESTRUCTION TO THE POINT OF DISINTEGRATION OF THE FILTER ELEMENT** is recorded.

The filter cartridge of course is toast. But the filter's inner core was destroyed also.

Initial signs of a compromised filter system is the filter vessel pressure



How does this happen? TOTAL NEGLECT



ANY QUESTIONS??